cERL 500 kV DC-gun Achievements, troubles, technical issues


e-Linac Reliability Workshop (remote) May 9-10, 2022

> Masahiro Yamamoto KEK

Outline

- Introduction: Compact-ERL & 500 kV DC-guns
- Achievements
 - HV conditioning for stable operation
 - 500 kV operation history
- Troubles
 - Vacuum leak
 - Serious discharge event
- Future technical issues
- Conclusion

Compact-ERL @ KEK




500 kV DC guns (1)



Developed at JAEA from 2007 ~ Installed compact-ERL at Oct. 2012. Beam test started from 2013 ~

500 kV DC guns (2)






Developed at KEK from 2009 ~

Achieved stable application of 500kV. Beam test started from 2015. Since 2016, it has been suspended due to budgetary concerns.

https://accelconf.web.cern.ch/erl2015/talks/tuiblh1021_talk.pdf

HV conditioning for stable operation (1)

1st DC-Gun results




M. Yamamoto and N. Nishimori, Appl. Phys. Lett. 109, 014103 (2016)

- The discharge voltage gradually increased while repeating many discharges.
- The discharge stop voltage has an important meaning.

6


HV conditioning for stable operation (2)



- The discharge stop voltage after HV conditioning is about 502 kV.
- Discharge occurs above 505 kV. The higher the voltage, the higher the discharge frequency.
- No discharge occurs at 500 kV.

ESD-ions may form a discharge circuit.


HV conditioning for stable operation (3)



- The discharge establishment threshold is defined as the product of the yield of ESD-ion and the ratio of SE by ion impact becomes 1.
- ESD-ion yield is decrease by discharge electron impact dose.

According to this mechanism, the discharge does not occur below the discharge stop voltage. (Discharge establishment threshold \cong Discharge stop voltage)


500 kV operation history (1)



- cERL DC-gun 500 kV Operation history from May 2017 to July 2020.
- 500kV holding time 1327 hours, total beam supply 1011 hours.
- During this time, there was no discharge caused by the electron gun.


Stable operation is guaranteed below the minimum discharge stop voltage.

500 kV operation history (2)




- The QE decreases by about 10% in about 2 hours.
- The increase in vacuum during operation is small.
- The radiation was mainly due to beam loss in the second arc section.

Trouble 1: Vacuum leaks



- Leakage at titanium-stainless steel large diameter flange connection.
- The cause is due to the difference in the coefficient of thermal expansion.
- Currently, VACSEAL is used to stop the leak as a first aid.
- Scheduled to be replaced with a thick gasket during this year's shutdown.

Trouble 2: Serious discharge event (1)




November 2020:

Feedback monitor line is disconnected during new inverter power supply adjustment. Turn on the power for test operation, the maximum output of \sim 600 kV can be applied instantly.

Frequent arc discharge occured for 20 second intermittently.

vacuum gauge stops abnormally and IGBT fails.


Trouble 2: Serious discharge event (2)



 No particular damage other than burning of the resistor.

•

Trouble 2: Serious discharge event (3)



After electrode wiping & HV conditioning


- The FE source disappears by wiping the electrodes. ٠
- 490kV DC-gun operation in February 2021. The FE source • reoccurs during additional conditioning.
- 390kV DC-gun operation after October 2021.


FE sources that could not be removed by conditioning could be removed by wiping with a lint-free wiper.

Future technical issues

HVPS output enhancement

- The drive frequency of the inverter is designed 40kHz for reduce the voltage ripple in HV output.
- Currently, the heat-problem of high-frequency transformers is bottleneck.
- Remodeling of a high frequency transformer is underway.





Photocathode lifetime improvement

- The lifetime of NEA-GaAs is short in a high-current operation.
- Considering switching photocathode from NEA-GaAs to CsK2Sb.
- Furthermore, R&D of photocathode protecting layer is underway in US-Japan cooperation.
- L. Guo et al., "Graphene as reusable substrate for bialkali photocathodes", Appl. Phys. Lett. 116 251903 (2020).
- F.Liu et al., "Photoemission from Bialkali Photocathodes through an Atomically Thin Protection Layer", ACS Appl. Mater. Interfaces 14 1710 (2022).

Summary

- ✓ Established HV conditioning method for stable operation.
 - ✓ Confirmed stable application of 500kV for both DC-guns.
 - ✓ 500 kV holding time for over 1300 hours.
 - ✓ 500 keV beam supply for over 1000 hours.
- \checkmark Achieved XHV condition by using titanium chamber.
 - ✓ An indispensable environment to use NEG-GaAs photocathode.
 - ✓ Large-diameter flanges leak at the connection with the SUS flange.
- ✓ Serious discharge event due to wiring error
 - Connection resistance burnout. No damage to the electron gun and high voltage generator.
 - $\checkmark\,$ FE source relapsed. FE source is removed by wiping the electrodes.
- ✓ Preparation for 10 mA CW-beam operation.
 - ✓ The problem of insufficient HV power output. Modification of high frequency transformer against heat generation.
 - ✓ Transition photocathode from NEA-GaAs to CsK2Sb.
 - ✓ R&D of the photocathode protecting layer is also underway with Japan-US cooperation.